STATE OF UTAH DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

1594 West North Temple - Suite 1210 Box 145801 Salt Lake City, Utah 84114-5801 Telephone: (801) 538-5291

Fax: (801) 359-3940

JAN 2 8 2005

ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I.	General Information
	1. Report Time Period: From (mo./yr.) _ <u>1-1-04</u> To (mo./yr.) <u>12-31-04</u>
	2. DOGM File Number (Mine No)S15/00 / 80
	3. Mine Name: BLACK BUTTE
	4. Mineral(s) Mined (or permitted to mine): Noble Metals
	5. Type of mine ☐ Surface Mine or ☐ Underground Mine
	6. Legal Description (Location of Lands Affected):
	_E1/4, _SE_1/4,1/4, Section _2, Township _20S_, Range14E_
	1/4,1/4,1/4, Section, Township, Range
	1/4,1/4,1/4, Section, Township, Range
7.	Name of Operator or Company: GOLDTERRA, INC.
	8. Permanent Street Address: 4088 East Airport Rd-PO Box 783
	City, State, Zip: Price, Utah 84501
	Phone: (435)636-8888 Fax: (435) 637-3888
	9. Company Representative (or designated operator):
	Name: Dan Sheppard
	Title: President
	Business Address: 4088 East Airport Road
	City, State, Zip: Price, Utah 84501
	Phone: (435)636-8888 Fax: (435)637-3888
	Please check if any of the above information has changed since previous year.
II.	Mining and Reclamation
	1. Was there any mine related activity during the past year? Yes ₺ No □
	2. If no - what was the last year of activity?
	3. If yes - how much ore or mineral was mined? Sampling of material only.
viewed	2/18/05 PBB Based on inspection, I question
hether	there was any activity at this site.
	,

4.	Briefly describe the type of work performed, volume of material moved, and any new or additional surface disturbances that occurred during the past year.
	N/A
5.	How much additional acreage was disturbed during the past year? Less than 1 Acre.
6.	How much acreage was reclaimed during the past year?None
7.	Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.
	N/A
one of the second se	
8.	What is the $\underline{\text{total}}$ disturbed acreage of entire project at years end $\underline{\text{Less than 1 Acre.}}$
9.	Briefly summarize any mining and/or reclamation plans for the upcoming year.
	Plan to excavate material and truck to the Pilot Mill
	1 <u>ocated at 4088 East Airport Road-Price, Utah at a rate</u>
	of 50 Tons per day.
NOTE:	Section III., "Additional Information" applies only to <u>large mining operations</u> .
III. <u>Additional</u>	Information - R647-4-121.2 and .3
1.	The operator shall include an updated map depicting surface disturbance and reclamation performed during the year, prepared in accordance with Rule R647-4-105.
2.	The operator shall keep and maintain timely records relating to his performance under the Act, and shall make these records available to the Division upon request.
IV. Signature	<u>e Requirement</u>
I here	eby certify that the foregoing is true and correct.
	Name (Typed or Print): Dan Sheppard
	Title of Operator: President
	Signature of Operator:
	Date: January 27, 2005

jb
o:\forms\reports\MR-AR